





Exterior window trim (like the photo above) needs to be carefully monitored for problems like missing calk, faded paint and warped boards. Moisture gets behind this causing moisture damage around windows.



Composite hardboard siding and trim is very susceptible to moisture damage. Do you like to paint? Leaking gutters do not help.