



Maintain screening material for attic ventilation and close up openings that would allow birds and bats to access attic space. Bathroom and Cook top vents increase moisture problems in the attic and a grease fire on the cook top could spread into the attic space.