



The photo above shows plumbing supply lines in the attic space. No heat, no insulation. Yes they froze and broke the following winter. Read your report carefully.

