



The photos above were taken in the basement of a home located in an area with ground water problems. A California investor owned the house. He had never seen the house in person. It was purchased to flip. The hired contractor/handy person was trying to hide the fungus growth with new carpet, paint and sheetrock. The plan was not working so well.

The photos below show an older house with many years of moisture problems in the basement area.

