



As the bathtub drained on the second floor, water started to exit out the cloths washer drain in the basement. The sewer line had some issues.

If you see this in your house, replace with a t fitting and a real shutoff valve. New homeowner did not. Water damage in basement six months later. When they go, they go!



How many layers

